



NOTE:  
ACTUAL LOCATION OF THE SIDE LAP SEALANT  
(INTERIOR JOINT OR EXTERIOR JOINT) MUST BE  
DETERMINED BY THE MECHANICAL ENGINEER AND OR  
ARCHITECT OF RECORD