## Page **CFR Insulated Roof Panel** MBCFR070 Date Rev **Hip** Jun '16 00 2" Long Tape Sealer $\frac{1}{4}$ " x 1" 7405 Place Under Male leg Urethane Tube Sealant and 3" Long Tape Sealer HW540 Each end at 1" x 1" 7405 Place on top Upslope Side of Closure of Male leg to Fill Voids as Necessary Fastener #4 Hip Trim F3371 $\frac{1}{4}$ -14 x $\frac{7}{8}$ " LL SD W/Washer at 6" O.C. Tape Sealer $\frac{1}{4}$ " x 1" 2§" 7405 Top and Bottom CFR Insulated Roof Panel of Closure Fastener #12A "Z" Closure F361 (Field 12-14 x 1" Pancake SD cut to Length and Bevel W/O Washer (2) per cut to fit Panel) Connection at Each Purlin Loose Fill Insulation or Hip Support Plate P141 Field Applied Foam (Field Notch at Purlins) (Not by MBCI) Non-Skinning Butyl Tube Through Panel Fastener IMP7100 3 Bead With Marriage W/ Sealing Washer at Bead to Panel Joint 6" O.C. Fastener #4 $\frac{1}{4}$ -14 x $\frac{7}{8}$ " LL SD W/Washer at 6" O.C. Hip Trim F3371 Z" Closure F361 Field cut to Length and Tape Sealer $\frac{1}{4}$ " x 1' Bevel cut to fit Panel 7405 Top of Closure Through Panel Fastener Urethane Tube Sealant W/ Sealing Washer at HW54\_ Each end at 6" O.C. Upslope Side of Closure to Fill Voids as Necessary Field Notch, Bend and Fasten Adjacent Zee Closures to Form Tape Sealer $\frac{1}{4}$ " x 1" a Weathertight Space at Base 7405 top and Bottom of Hip Trim end of Closure